Norfolk Southern SD38-2 Rebuild

From SD40-2 By Norfolk Southern at Juniata

NS 3821

6/04 and 5/13 1 unit

Bld	Frame	Bld			Rbld		Rbld		
No.	No.	Date	Blt As	2nd No.	Date	Rblt As	Date	Rblt As	Notes
796353-18	796353-18	Dec-80	NW 6206	NS 6206	Jun-04	NS 3821	May-13	3 NS 6206	
2004 Notes:									
Turbo replac	ed with blower	s, resultin	g in 2,000 h	р					
Middle radia	tor fan remove	d							
Converted to	slug master fo	or RPU6 s	lugs						
Air condition	er installed								
Changed fro	m long hood fo	rward to	short hood fo	orward					
Not cab sign	al or LSL equip	ped							
2013 Notes:									
Turbo reinsta	alled, resulting	in 3,000 ł	пр						
Middle radia	tor fan reinstall	ed							
Abbreviatio	ns:								
NS	Norfolk South	nern							
NW	Norfolk & We	stern							
Sources:									
Norfolk Sout	hern Locomotiv	ve Directo	orv 1998-199	9 bv Paul With	hers				
NSDash9.co			,	,					
www.Altoo	onaWorks.ir	<u>ifo</u>							
	2008-2013 L.R		All rights res	erved.					